

d his

(FILE 'HOME' ENTERED AT 17:26:34 ON 14 DEC 2001)

FILE 'REGISTRY' ENTERED AT 17:28:56 ON 14 DEC 2001
L1 0 (.1<SN<1 AND .1<AG<1 AND 2<FE<3 AND 0<ZN<.5 AND 0<P<.2 AND 0<CR
L2 3 (.1<SN<1 AND .1<AG<1 AND 2<FE<3 AND 0<ZN<1 AND 0<MG<1 AND 50<CU

FILE 'HCAPLUS' ENTERED AT 17:31:29 ON 14 DEC 2001
L3 3 L2

FILE 'REGISTRY' ENTERED AT 17:33:47 ON 14 DEC 2001
L4 84 (1<FE<3 AND 0<ZN<1 AND 0<P<.5 AND 50<CU)/MAC

FILE 'HCAPLUS' ENTERED AT 17:34:43 ON 14 DEC 2001
L5 271 L4
L6 22347 (COPPER OR CU) AND (ZINC OR ZN) AND (PHOS? OR P) AND (IRON OR F
L7 61 L5 AND L6
L8 968 TENSILE? AND IACS
 SELECT L3 IPC 2
L9 93581 E1-4
L10 728 L9 AND L8

FILE 'REGISTRY' ENTERED AT 17:36:37 ON 14 DEC 2001
L11 39119 (50<CU)/MAC

FILE 'HCAPLUS' ENTERED AT 17:36:56 ON 14 DEC 2001
L12 488 L11 AND L10
L13 487 L12 AND (COPPER OR CU)
L14 99817 HIGH(2A) ELECTR?
L15 170 L13 AND L14